

19-1255

CASING USED 1  yes 2  no

- Trench Wall
- Under Floor
- Under Airway Drive
- Vented
- Other

NOTE: Show Casing on sketch

Document  yes  no  
 Building  Old  New

Fittings )  No outside  
 Coated with )  plastic tape

VALVE LOCATION

- R/w cover at Curb
- R/w cover at Main
- Buried at Main
- Other

Ft. \_\_\_\_\_

Ft. \_\_\_\_\_

Pilgrim LN N



93 AVE. N.

← 27' →



16'

78'

10050

↑ SET  
 ↑ SWEEP  
 ↓ BEND  
 BACK

Conditions in yard (Mark only one) 1  No Sod 2  Sod 3  Solid pavement

Obstacles 1  None 2  Concrete Sidewalk or Curb 3  Other, specify \_\_\_\_\_

Soil (Mark only one) 1  Peat or Loam 2  Sand 3  Clay 4  Gravel 5  Rock or Fill

Method of ditching. Ditcher: 1  Used all the way 2  Used partly 3  Not used

Sq. ft. of Sod moved or replaced NONE Sq. ft. (Enter Sq. ft. or write none)

Paving 1  Concrete 2  Bituminous: Permanent  
 3  Oiled: Non Permanent 4  Other - Not paved

Paving in Street, size disturbed NONE

①