


CenturyLink Constant Job Order/Maintenance Work Authorization

Company: 1866 Exchange 579 Osseo Service Order#
 Work Activity: Drop-Buried ~~Cable~~ Fiber Capital Maintenance
 Customer Name: Kyle BrendenueHL Phone#
 Address: 17060 78 Ave N One Call Ticket#
 Location/Directions:
 Description of Work or Special Instructions:

DOR/TOG Yes ___ No Permit: Yes No ___ Bore: Yes ___ No CBR#
 Employee Name: ~~Brandon Smith~~ Roy Miller Employee Contact#: ~~612-298-7599~~ 612-219-9122

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty	Actual Qty	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennepin					
Township					
Section					
Range					
GPS Reading					

Nearest cross st. Plat Page Map#
 Damaged facility # Tax Code



Originated By: _____ Date: _____ Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____