



Local
CMS#

CMS# 6220810 HELD ORDER PERMI



CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name Damon Cross Phone# 763-425-0041
 Address 12005 85 PL N. One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions plow 300' from NID to new MST. Place MST. This customer is waiting for service.
 This is GPON customer.

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes x No ___ CBR# 612-440-4036
 Employee Name Kris Townsend Employee Contact# 612-715-9060

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____
SKETCH



300' total length
customers have
sprinklers

Originated By: Townsend Date: 9/28/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____