


Revised 4-6-18		CMS#	19072928 HELD / PERMIT	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>				
Company	T600	Exchange Name	MAPLE GROVE	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name				Phone#
Address	7333 Jewel Ln N		One Call Ticket#	
City & Zip	Maple Grove MN			
Location/Directions	Bore 190 ft from ped to MST. 5 port MST required			

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	
Tech Name and Tech #	Don Evans			Employee Contact#	6124303133		

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot# 33	SEB3-22	BSW-3 & plow plcmt		
	SEB3-221	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop		
Township:	BM61(1.25)SEB	BSW Bore footage	190	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR I	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	BM61(3)D-Rock CBL	Rock Boring		
	Permit	Permit	1	
Nearest cross st.			Plat Page	Map#



Originated By:	Don Evans	Date:	4/29/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	