


Revised 1-15-2019 CMS# 19072652 HELD / PERMIT

CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name	MAPLE GROVE - MPGVMNXA	Service Order#	1538347677
Work Activity	Fiber-Buried	Capital	Y	Maintenance	
Customer Name	Beth Lashinski			Phone#	
Address	11694 85th Place N			One Call Ticket#	
City & Zip	Maple Grove, MN55369				
Location/Directions					
Description of Work or Special Instructions					

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	
Tech Name and Tech #				Employee Contact#	763-807-0943		

Sketch (Include Cntr Line & Pedestal)		Material/Labor Units		Footage/Quantity	Comments
		Description	Notes		
Cntr Line foot		SEB3-22	BSW-3 & plow plcmt		0
		SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	11678	SEPCUTOVER	CUTOVER BSW		0
Parish/County		BM83	BSW guard at house		0
		XXSEB-GL	Remove temp drop		0
Township:		BM61(1.25)SEB	BSW Bore footage	100	
Section		SEBO PER FT LBR	Fiber & plow plcmt	60	
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt		
		SEB6-22	BSW-6 & plow plcmt		0
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge	1	
		Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	Forestview Ln		Plat Page		Map#



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____		

Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker	