


Revised 1-15-2019

CMS#

19073566 HELD / PERMIT

CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name	MAPLE GROVE - MPGVMNXA		Service Order#	1538681727
Work Activity	Fiber-Buried	Capital	Y	Maintenance		
Customer Name	Joseph Molinaro			Phone#		
Address	10861 Sundance BLVD N			One Call Ticket#		
City & Zip	Maple Grove, MN 55369					
Location/Directions						
Description of Work or Special Instructions						
Held Order	Y	Permit:	Y	Bore:	Y	CBR#
Tech Name and Tech #				Employee Contact#	763-807-0943	
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments	
	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt				
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	SEPCUTOVER	CUTOVER BSW				
Parish/County	BM83	BSW guard at house				
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage		120		
Section	SEBO PER FT LBR	Fiber & plow plcmt		40		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt				
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	Trip Charge	Trip Charge				
	Permit	Permit			Any placement within the ROW requires a permit	
Nearest cross st.	108th Place			Plat Page		Map#



Originated By: _____ Date: _____ Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	