


Revised 1-15-2019				CMS#	19081193 HELD PERMIT
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>					
Company	T866	Exchange Name	MAPLE GROVE - MPGVMNXA	Service Order#	1540182482
Work Activity	Fiber-Buried	Capital	Y	Maintenance	
Customer Name	Marie Jennings			Phone#	
Address	7520 Walnut Grove Ln N			One Call Ticket#	
City & Zip	Maple Grove MN 55311				
Location/Directions					
Description of Work or Special Instructions					
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	Les Peterson			Employee Contact#	763-807-0943
Sketch	Material/Labor Units				Footage/Quantity
(Include Cntr Line & Pedestal)	Description	Notes			Comments
Cntr Line foot#	SEB3-22	BSW-3 & plow plcmt			
	SEB3-22T	BSW-3 & hand dig plcmt			
Ped#	7512	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house		1	
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage		95	
Section	SEBO PER FT LBR	Fiber & plow plcmt			
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		50	
	SEB6-22	BSW-6 & plow plcmt			
	BM2(5/8)(8)	Ground Rod			
	Trip Charge	Trip Charge		1	
	Permit	Permit		1	Any placement within the ROW requires a permit
Nearest cross st.	75th Ave N			Plat Page	Map#



Proceed with order and place temp

This is an estimated dollar amount you can quote the customer. This is not exact and it's only to be used to see if the customer is interested to proceed.

**FALSE**

Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	