


Revised 4-6-18		CMS#	19025617 HELD PERMIT		
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange Name	OSSEO	Service Order#	1530364622
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	MICHAEL RIVERA		Phone#	7634241161	
Address	9565 103RD AVE N		One Call Ticket#		
City & Zip	MAPLE GROVE 55369				
Location/Directions					
Description of Work or Special Instructions					

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	3473169524	
Tech Name and Tech #	DEXTER KOEPP		Employee Contact#	651-302-5304				
Sketch	Material/Labor Units		Footage/Quantity	Comments				
(Include Cntr Line & Pedestal)	Description	Notes						
Cntr Line Footg	33	SEB3-22	BSW-3 & plow picmt					
		SEB3-22I	BSW-3 & hand dig picmt					
Ped#	ONU	SEPCUTOVER	CUTOVER BSW					
Parish/County	Hennepin	BM83	BSW guard at house	1				
		XXSEB-GL	Remove temp drop					
Township:		BM61(1.25)SEB	BSW Bore footage	150				
Section		SEBO PER FT LBR	Fiber & plow picmt					
Range		SEBO PER FT LBR T	Fiber & hand dig picmt	50				
		SEB6-22	BSW-6 & plow picmt					
		BM2(5/8)(8)	Ground Rod					
		Trip Charge	Trip Charge	1				
		BM61(3)D-Rock CBL	Rock Boring					
		Permit	Permit	1				
Nearest cross st.	LANCASTER		Plat Page		Map#			



Originated By:	DEXTER KOEPP	Date:	2/12/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	