


Revised 4-6-18		CMS#	18231611 HELD PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization				
Company	T600	Exchange Name	MAPLE GROVE	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	marlin brandua		Phone#	
Address	10703 108th pl n		One Call Ticket#	
City & Zip	maple grove 55369			
Location/Directions				
Description of Work or Special Instructions	bore under two driveways and hand dig to the house there is a flab buy the air conditioner			
Held Order	Y	Permit:	Y	Bore:
Tech Name and Tech #	cory cook		Employee Contact#	7632287153
Sketch	Material/Labor Units			
(Include Cntr Line & Pedestal)	Description	Notes	Footage/Quantity	Comments
Cntr Line Foot#	33	SEB3-22	BSW-3 & plow picmt	
		SEB3-22I	BSW-3 & hand dig picmt	
Ped#	125383	SEPCUTOVER	CUTOVER BSW	
Parish/County		BM83	BSW guard at house	1
		XXSEB-GL	Remove temp drop	
Township:		BM61(1.25)SEB	BSW Bore footage	100
Section		SEBO PER FT LBR	Fiber & plow picmt	
Range		SEBO PER FT LBR T	Fiber & hand dig picmt	70
		SEB6-22	BSW-6 & plow picmt	
		BM2(5/8)(8)	Ground Rod	
		Trip Charge	Trip Charge	1
		BM61(3)D-Rock CBL	Rock Boring	
		Permit	Permit	1
Nearest cross st.			Plat Page	Map#

corrilation id# 3575366

bore 100 feet
hand dig fiber 70 feet
total drop 170



Originated By:		Date:	12/7/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	