



Local
CMS#


CMS#

CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name L C Harris Phone# 763-425-5686
 Address 9936 108 AVE N One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions Place 1 MST and 1 drop to home. From ONU 321 9052 plow under 108 Ave. N. across street and place MST, 50'. Then plow 52" from new MST to side of house where there is a white flag. GPON install
 DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes x No ___ CBR# 763-301-1752
 Employee Name Kris Townsend Employee Contact# 612-715-9060

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____
SKETCH Tax Code _____



Originated By: <u>Townsend</u>	Date: <u>9/30/16</u>	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	_____

Inspection notes: _____