


		Local Exch#			CMS#		
CenturyLink BSW Order/Maintenance Work Authorization							
Company	T600	Exchange				Service Order#	1401095707
Work Activity				Capital	Y	Maintenance	N
Customer Name	Anh Nguyen			Phone#	763-416-3753		
Address	16988 78th ave n			One Call Ticket#			
City & Zip	maple grove						
Location/Directions	GPS						
Description of Work or Special Instructions							
place 170' fiber drop with 2 DW bored for 25' each							
Held Order ?	NO	Permit:	NO	Bore:	NO	CBR#	
Employee Name	MER064519			Employee Contact#	7632288645		
Material/Labor Units				Est	Actual	Placed by	
(Include Cntr Line & Pedestal)	Description	Notes		Qty.	Qty	(Foreman/Crew Name)	
Cntr Line foot	33	SEB3-22	Place 3 pair BSW				
Ped#	124133	SEPCUTOVER	CUTOVER BSW				
Parish/County	Hennepi	BM83	BSW guard at house				
		XXSEB-GL	Remove temp drop				
Township:	na	BM61(1.5)D	BSW Bore required				
Section	na	SEB3-22T	Hand Dig				
Range	na	SEBOP2	Fiber Drop				
Nearest cross st.	GPS			Plat Page	GPS	Map#	GPS
Damaged facility #							
SKETCH							



Originated By:	MER064519	Date:	9/30/16	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Inspection Notes: MetroBSW @centurylink.com							
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline:		4. Nearest State Hwy mile marker					