


Revised 4-6-18		CMS#	19086088 PERMIT
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>			
Company	T600	Exchange Name	MAPLE GROVE
Work Activity	Fiber-Buried	Capital	Y
Customer Name	BENJAMIN NELSON	Phone#	763-416-0927
Address	10755 SUNDANCE BLVD N	One Call Ticket#	
City & Zip	Maple Grove, MN		
Location/Directions			
Description of Work or Special Instructions			
bore 120 then hand dig 55', Total 175'. This is fiber. Pick up temp and cut over.			
Also straighten and fix fiber ped when on site. Currently there is no yard.			

Held Order	N	Permit:	Y	Bore:	Y	CBR#	612-276-2704
Tech Name and Tech #	Kris Townsend		Employee Contact#	612-715-9069			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot# 33	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop	1	
Township:	BM61(1.25)SEB	BSW Bore footage	120	
Section	SEBO PER FT LBR	Fiber & plow plcmt	55	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	BM61(3)D-Rock CBL	Rock Boring		
	Permit	Permit	1	
Nearest cross st.			Plat Page	Map#



Originated By:	Townsend	Date:	5/16/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	

