


Revised 1-15-2019				CMS#	19091116 PERMIT
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>					
Company	T866	Exchange Name	MAPLE GROVE - MPGVMNXA		Service Order# 1541556952
Work Activity	Fiber-Buried		Capital	Y	Maintenance
Customer Name	Tori Myslajek			Phone#	
Address	7600 Urbandale Ln N			One Call Ticket#	
City & Zip	Maple Grove, MN 55311				
Location/Directions					
Description of Work or Special Instructions					
Held Order	N	Permit:	Y	Bore:	Y
Tech Name and Tech #	Les Peterson		Employee Contact#	763-807-0943	
Sketch	Material/Labor Units			Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description		Notes		
Cntr Line foot#	SEB3-22	BSW-3 & plow plcmt			
	SEB3-22T	BSW-3 & hand dig plcmt			
Ped#	7588	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house		1	
	XXSEB-GL	Remove temp drop		350	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage		85	
Section	SEBO PER FT LBR	Fiber & plow plcmt			
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		80	
	SEB6-22	BSW-6 & plow plcmt			
	BM2(5/8)(8)	Ground Rod			
	Trip Charge	Trip Charge			
	Permit	Permit			Any placement within the ROW requires a permit
Nearest cross st.	75th Place N		Plat Page	Map#	



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					