

Revised 1-15-2019

CMS#

19109621 - HELD

CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name		Service Order#	1544072942
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	BRIAN WILLIAMS			Phone#	7633151269
Address	10440 NATHAN LN N			One Call Ticket#	
City & Zip	MAPLE GROVE, MN 55369-2959				
Location/Directions	GPS				
Description of Work or Special Instructions	See sketch for details				
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	AA10109			Employee Contact#	763-228-8645

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	33	SEB3-22 SEB3-22T		BSW-3 & plow plcmt BSW-3 & hand dig plcmt
Ped#	MST	SEPCUTOVER		CUTOVER BSW
Parish/County		BM83	1	BSW guard at house
Township:	NA	XXSEB-GL		Remove temp drop
Section	NA	BM61(1.25)SEB	95	BSW Bore footage
Range	NA	SEBO PER FT LBR T	155	Fiber & plow plcmt
		SEB6-22		Fiber & hand dig plcmt
		BM2(5/8)(8)		BSW-6 & plow plcmt
		Trip Charge	1	Ground Rod
		Permit	1	Trip Charge
Nearest cross st.		NA		Permit



Originated By:	AA10109	Date:	6/20/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					

Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	