


SKETCH



83rd Av N.

PEONY LA.



Surface Disturbed at Main

- Concrete
- Bituminous
- Oiled
- Other \_\_\_\_\_
- Boulevard

Basement  
Yes  No

Building  
Old  New

Casing  
Yes  No

Show casing on sketch

Coatings  
Steel Pipe:

- Cor-Bond
- Scotchkote #202
- X-Thru-Coat
- Coal Tar Enamel
- Flexclad
- Other \_\_\_\_\_

Fittings:  
Black Mastic   
Plastic Tape

Soil CLAY

Valve in Roadway Cover  
Yes  No

Type \_\_\_\_\_ Size \_\_\_\_\_

Valve loc. Blvd.  Str.   
Main loc. Blvd.  Str.

\_\_\_\_ ft. \_\_\_\_\_  
\_\_\_\_ ft. \_\_\_\_\_

Service Location

Right   
Left   
Front