


Revised 4-6-18		CMS#		19094042 PERMIT	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>					
Company	T600	Exchange Name	MAPLE GROVE	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	
Customer Name	Maple Grove Park And Rec			Phone#	7634258613
Address	10122 104th Ave N			One Call Ticket#	
City & Zip	Maple Grove MN				
Location/Directions					
Description of Work or Special Instructions	Plow 1145 ft of fiber from ped to nid				

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	6513127065	
Tech Name and Tech #	Don Evans		Employee Contact#		6124303133			
Sketch	Material/Labor Units							
(Include Cntr Line & Pedestal)	Description	Notes	Footage/Quantity	Comments				
Cntr Line Footg	33	SEB3-22	BSW-3 & plow picmt					
		SEB3-22I	BSW-3 & hand dig picmt					
Ped#	43409035	SEPCUTOVER	CUTOVER BSW					
Parish/County		BM83	BSW guard at house	1				
		XXSEB-GL	Remove temp drop					
Township:		BM61(1.25)SEB	BSW Bore footage	245				
Section		SEBO PER FT LBR	Fiber & plow picmt					
Range		SEBO PER FT LBR T	Fiber & hand dig picmt	900				
		SEB6-22	BSW-6 & plow picmt					
		BM2(5/8)(8)	Ground Rod					
		Trip Charge	Trip Charge	1				
		BM61(3)D-Rock CBL	Rock Boring					
		Permit	Permit	1				
Nearest cross st.				Plat Page	Map#			



Originated By:	Don Evans	Date:	5/29/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	