


Revised 4-6-18				CMS#	19143407 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization						
Company	T600	Exchange Name	MAPLE GROVE		Service Order#	
Work Activity	Fiber-Buried		Capital	Y	Maintenance	
Customer Name	kyle boughner			Phone#	7633153486	
Address	8574 deerwood ln			One Call Ticket#		
City & Zip	maple grove					
Location/Directions						
Description of Work or Special Instructions	plow in 130ft of fiber drop with 20ft driveway bore					
Held Order	N	Permit:	Notes	Bore:	Y	CBR# 7632347492
Tech Name and Tech #	pat nathe			Employee Contact#	6127159213	
Sketch	Material/Labor Units			Footage/Quantity	Comments	
(Include Cntr Line & Pedestal)	Description	Notes				
Cntr Line Footg	33	SEB3-22	BSW-3 & plow picmt			
		SEB3-22I	BSW-3 & hand dig picmt			
Per#	18582	SEPCUTOVER	CUTOVER BSW			
Parish/County	Hennep	BM83	BSW guard at house		1	
		XXSEB-GL	Remove temp drop			
Township:		BM61(1.25)SEB	BSW Bore footage		20	
Section		SEBO PER FT LBR	Fiber & plow picmt		130	
Range		SEBO PER FT LBR T	Fiber & hand dig picmt			
		SEB6-22	BSW-6 & plow picmt			
		BM2(5/8)(8)	Ground Rod			
		Trip Charge	Trip Charge			
		BM61(3)D-Rock CBL	Rock Boring			
		Permit	Permit			
Nearest cross st.	forestview			Plat Page	Map#	



Originated By:	pat nathe	Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	