Revised 4-6-18										CMS#	19151317 HELD PER				
					Cen	turyLink E	3SW Or	der/N	laintena	nce Wo	rk Au	thoriza	ation		
Company	T600 Exchange Name MAPLE GROVE							Service Order#							
Work Activity	-Buried Copper						Capit	al	Y Maintenan		ance				
Customer Name)	AT&T voice										Ph	one#	7634253300	
Address		6903 crest dr									One Call Ticket#				
City & Zip		maple grove											<u>n</u>		
Location/Directi	ons	west of	east fish	lake rd			5								
Description of We	ork or Spe	cial Instr	uctions		plow	in 180ft drop	cooper.	with 3	Oft drivewa	av bore.					
										,					
Held Order	N Permit:		Notes Bore: Y				CBR# 7632277221		221						
Tech Name and Tech #		pat nathe							Employe	e Contact#	# 61271592			213	
Sketch		Material/Labor Units							Factors (Ourseiter						
(Include Cntr Line & Pedestal)		Description				Notes			Footage/Quanity		Comments				
Cntr Line foota	33	SEB3-22				BSW-3 & plow plcmt			1	80					
		SEB3-22T				BSW-3 & hand dig plcmt									
	1373-9017		SEPCUTOVER			CUTOVER BSW				1					
Parish/County	Hennep					BSW guard at house									
						Remove temp drop									
l ownship:		BM61(1.25)SEB			BSW Bore footage				30						
Section		SEBO PER FT LBR			Fiber & plow plcmt										
Range		SEBO PER FT LBR T				Fiber & hand dig plcmt									
		SEB6-22				BSW-6 & plow plcmt									
		(-)(-)				Ground Rod									
						Trip Charge				1					
						Rock Boring									
	Permit				Permit										
Nearest cross st.		sunnyslope dr						Plat	Page			Map#			

