


CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name	OSSEO - OSSEMNXO	Service Order#	1552974407
Work Activity	Fiber-Buried	Capital	Y	Maintenance	
Customer Name	GREG PAULSON			Phone#	7633150413
Address	11028 108TH AVE N			One Call Ticket#	
City & Zip	Maple Grove MN 55369				
Location/Directions	North of Zachary and 610				
Description of Work or Special Instructions	new fiber drop for held order				

Held Order	y	Permit:	y	Bore:	y	CBR#	612-759-8899
Tech Name and Tech #	Ryan Einerwold			Employee Contact#	763-464-7242		

Sketch		Material/Labor Units		Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes			
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt			
	SEB3-22T	BSW-3 & hand dig plcmt			
Ped#	SEPCUTOVER	CUTOVER BSW			
Parish/County	BM83	BSW guard at house			
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage		110	
Section	SEBO PER FT LBR	Fiber & plow plcmt		52	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt			
	SEB6-22	BSW-6 & plow plcmt			
	BM2(5/8)(8)	Ground Rod			
	Trip Charge	Trip Charge		1	
	Permit	Permit		1	Any placement within the ROW requires a permit

Nearest cross st.	WELLINGTON LANE	Plat Page		Map#	
--------------------------	-----------------	------------------	--	-------------	--



Originated By:	Ryan Einerwold	Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					

Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	