

Revised 1-15-2019		CMS#		19173661 - HELD	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T866	Exchange Name	OSSEO - OSSEMNXO	Service Order#	1553815032
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	CHRIS HERMAN		Phone#	7633151932	
Address	9904 107TH PL N		One Call Ticket#		
City & Zip	MAPLE GROVE, MN 55369-2726				
Location/Directions	GPS				
Description of Work or Special Instructions SEE SKETCH FOR DETAILS					
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	AA10109	Employee Contact#	763-228-8645		

Sketch (Include Cntr Line & Pedes)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot: 33	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped# 321-9025	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township: NA	BM61(1.25)SEB	BSW Bore footage	135	
Section NA	SEBO PER FT LBR	Fiber & plow plcmt	310	
Range NA	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	NA	Plat Page	NA	Map# NA



Originated By:	AA10109	Date:	9/13/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to: MetroBSW@Centurylink.com							
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					