


Revised 4-6-18		CMS#	19180346 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization				
Company	T600	Exchange Name	MAPLE GROVE	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	tina fredericksen		Phone#	7633154653
Address	8590 deerwood ln		One Call Ticket#	
City & Zip	maple grove			
Location/Directions	mills creek			
Description of Work or Special Instructions				
plow in200ft drop 2 driveway bores				
Held Order	N	Permit:	Notes	Bore: Y
Tech Name and Tech #	pat nathe		Employee Contact#	6127159213
Sketch				
Material/Labor Units				
(Include Cntr Line & Pedestal)	Description	Notes	Footage/Quantity	Comments
Cntr Line foot#	33	SEB3-22	BSW-3 & plow picmt	
		SEB3-22I	BSW-3 & hand dig picmt	
Ped#	9999	SEPCUTOVER	CUTOVER BSW	
Parish/County	Hennepin	BM83	BSW guard at house	1
		XXSEB-GL	Remove temp drop	
Township:		BM61(1.25)SEB	BSW Bore footage	40
Section		SEBO PER FT LBR	Fiber & plow picmt	160
Range		SEBO PER FT LBR T	Fiber & hand dig picmt	
		SEB6-22	BSW-6 & plow picmt	
		BM2(5/8)(8)	Ground Rod	
		Trip Charge	Trip Charge	1
		BM61(3)D-Rock CBL	Rock Boring	
		Permit	Permit	
Nearest cross st.	forestview		Plat Page	Map#

CONTACT CUSTOMER 1ST



Originated By:	pat nathe	Date:	Completed By:	Date:
Authorized By: (APS)		Date:	Inspected By:	Date:
Authorized By: (AOM)		Date:		
Email sketch to: MetroBSW@Centurylink.com				
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection		
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker		