

Revised 1-15-2019

CMS#


19184079 HELD

CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name		Service Order#	1554017347
Work Activity	Fiber-Buried	Capital	Y	Maintenance	
Customer Name	MICHELE STENDAL			Phone#	7634940057
Address	8153 ARROWWOOD LN N MAPLE GROVE, MN			One Call Ticket#	
City & Zip	Maple Grove MN 55369				
Location/Directions	West off 82nd and Hemloch				
Description of Work or Special Instructions	held order drop placement to nid hung near central air unit				

Held Order	Yes	Permit:	No	Bore:	Yes	CBR#	
Tech Name and Tech #	Ryan Einerwold			Employee Contact#	763-464-7242		

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	35	
Section	SEBO PER FT LBR	Fiber & plow plcmt	45	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit		Any placement within the ROW requires a permit
Nearest cross st.	82nd		Plat Page	Map#



nid is already hung near central air unit

Originated By: Ryan Einerwold Date: 10/2/19 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	