

Permit Labor Design

JT 21269  
Track

Issued  
T-Ray  
10/18/16  
464'

# Comcast

Plant Maintenance Request **V5** Job number **NW427**  
 Node DA124 City Maple Grove Date 10/13/2016  
 Address 825 Alvarado Ln N Cross Street 97th pl n  
 Maint tech Name: Nathan Krick Tech # 1570 Phone: (612) 875-6664

Span type  span (temped)  Span (no temp)  Digup  Other  Spring

Priority 1  a.) Customer Impacting Issue b.) Vulnerable temp c.) TIE related ticket  
 2  a.) Aerial temp cables b.) Any temp - no liability issues  
 3  a.) Identified cables - no customer impact b.) Leaks - no customer impact

Work is needed :  ASAP  Normal

Work is a :  Cable Replacement  Broken Lashing  Pole Transfer  Damaged Ped  
 Utility Violation  Storm Damage  Leakage  Other

MDU? (Attachments, lockboxes, cable on the roof)  Yes  No

Type of Cable  Aerial  UG Bare  UG Duct  Self Support Size: 0.875

Footage: Aerial Underground 464'

Bore Required  Yes  No If yes, what type and how many 4 driveway, 1 street

Is there fiber in the package?  Yes  No How Many Fibers? \_\_\_\_\_

Cause for referral:  RTM  Leakage  Rapid Resolve (Flux)  Damage/Outage  NH/MH  LPI  
 (check one)  Priority plant fault  Service Call Alert  PI Ticket  Other  CM Suckout

### Explain Damage:

at least 300', closest ped is 464'. Losing about 15dB by the time it reaches next amp. I was able to turn up levels at the amp temporarily.

### Maintenance Department Use Only

Date Received \_\_\_\_\_ Capitol  Yes  No Maint complete   
 Total Tech Hours \_\_\_\_\_ Techs \_\_\_\_\_

### A Highlighted plant map must be attached

To help expedite this maintenance request, information on this form needs to be filled out completely and signed by a technician and a supervisor requesting the repair.

Tech Signature \_\_\_\_\_ Tech # \_\_\_\_\_ Date \_\_\_\_\_  
 Supervisor Signature \_\_\_\_\_

### Construction Department Use Only

Date received \_\_\_\_\_ Project # \_\_\_\_\_  Construction Completed  
 Coordinator Signature \_\_\_\_\_ Supervisor Signature \_\_\_\_\_




CD RD 101

CITY OF CORCORAN

CITY OF MAPLE GROVE

186' 0/0 215' 0/0 217' 0/0 196' 0/0 202' 0/0 197' 0/0 204' 0/0 197' 0/0 136'

DATA SHEET	
188	217.2
189	217.2
190	217.2
191	217.2
192	217.2
193	217.2
194	217.2
195	217.2
196	217.2
197	217.2
198	217.2
199	217.2
200	217.2
201	217.2
202	217.2
203	217.2
204	217.2
205	217.2
206	217.2
207	217.2
208	217.2
209	217.2
210	217.2
211	217.2
212	217.2
213	217.2
214	217.2
215	217.2
216	217.2
217	217.2
218	217.2
219	217.2
220	217.2



*New on trunk*  
*Block on splice in ped*  
 dig up tail and splice in new

DATA SHEET	
188	217.2
189	217.2
190	217.2
191	217.2
192	217.2
193	217.2
194	217.2
195	217.2
196	217.2
197	217.2
198	217.2
199	217.2
200	217.2
201	217.2
202	217.2
203	217.2
204	217.2
205	217.2
206	217.2
207	217.2
208	217.2
209	217.2
210	217.2
211	217.2
212	217.2
213	217.2
214	217.2
215	217.2
216	217.2
217	217.2
218	217.2
219	217.2
220	217.2