



Local
CMS#

16230763 HELD ORDER PERMIT


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital Maintenance _____
 Customer Name Stephanie Skulan Phone# 763-416-0831
 Address 10655 104th. Pl. N., Maple Grove One Call Ticket# _____
 Location/Directions _____
 Description of Work or Special Instructions _____

DOR/TOG Yes ___ No Permit: Yes No ___ Bore: Yes ___ No CBR# 715-292-1604
 Employee Name Brandon Smith Employee Contact# 612-296-7599

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County _____					
Hennipen _____					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____
 SKETCH _____ Tax Code _____



Originated By: _____ Date: _____ Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____