

Revised 1-15-2019				CMS#		19224412	
CenturyLink BSW Order/Maintenance Work Authorization							
Company		T866 Exchange Name OSSEO - OSSEMNXO		Service Order#			
Work Activity		Fiber-Buried		Capital Y		Maintenance	
Customer Name		Steve Houfek		Phone#		7634161449	
Address		9714 103rd Ave N		One Call Ticket#			
City & Zip		Maple Grove Mn					
Location/Directions							
Description of Work or Special Instructions				Plow 120 ft of fiber from ped to nid. 90 ft right of way bore required			
Held Order		N		Permit: Y		Bore: Y	
Tech Name and Tech #		Donald Evans		Employee Contact#		7632577746	
Sketch		Material/Labor Units		Footage/Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes			
Cntr Line foot		SEB3-22		BSW-3 & plow plcmt			
		SEB3-22T		BSW-3 & hand dig plcmt			
Ped#		SEPCUTOVER		CUTOVER BSW		1	
Parish/County		BM83		BSW guard at house		1	
		XXSEB-GL		Remove temp drop		1 Footage when temp can't be re-used	
Township:		BM61(1.25)SEB		BSW Bore footage		90	
Section		SEBO PER FT LBR		Fiber & plow plcmt			
Range		SEBO PER FT LBR T		Fiber & hand dig plcmt		20	
		SEB6-22		BSW-6 & plow plcmt			
		BM2(5/8)(8)		Ground Rod			
		Trip Charge		Trip Charge		1	
		Permit		Permit		1 Any placement within the ROW requires a permit	
Nearest cross st.				Plat Page		Map#	
<p style="text-align: center;">103rd Ave N</p>							
Originated By:		Donald Evans		Date: 11/27/19		Completed By: _____	
Authorized By: (APS)		_____		Date: _____		Inspected By: _____	
Authorized By: (AOM)		_____		Date: _____		_____	
Email sketch to: MetroBSW@Centurylink.com							
1. Distance of the bury in Right-of-Way		_____		3. Distance to the nearest intersection		_____	
2. Distance from the terminal to the centerline		_____		4. Nearest State Hwy mile marker		_____	