

Revised 1-15-2019

CMS#

20009839 HELD

CenturyLink BSW Order/Maintenance Work Authorization

Company	T866	Exchange Name	OSSEO - OSSEMNXO	Service Order#	1565767587
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	GLORIA TOLEDO			Phone#	7633150207
Address	8118 BALSAM LN N			One Call Ticket#	
City & Zip	MAPLE GROVE 55369				
Location/Directions					
Description of Work or Special Instructions	See sketch for details				
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	AB71973		Employee Contact#	651-302-5304	

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	33	SEB3-22		BSW-3 & plow plcmt
		SEB3-22T		BSW-3 & hand dig plcmt
Ped#		SEPCUTOVER		CUTOVER BSW
Parish/County		BM83	1	BSW guard at house
		XXSEB-GL		Remove temp drop
Township:	NA	BM61(1.25)SEB	60	BSW Bore footage
Section	NA	SEBO PER FT LBR		Fiber & plow plcmt
Range	NA	SEBO PER FT LBR T	30	Fiber & hand dig plcmt
		SEB6-22		BSW-6 & plow plcmt
		BM2(5/8)(8)		Ground Rod
		Trip Charge	1	Trip Charge
		Permit	1	Permit
Nearest cross st.		NA	Plat Page	NA
			Map#	NA



Originated By:	AB71973	Date:	1/16/20	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					

Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	