


Revised 4-6-18		CMS#	20018857
CenturyLink BSW Order/Maintenance Work Authorization			
Company	T600	Exchange Name	MAPLE GROVE
Work Activity	Fiber-Buried	Capital	Y
Customer Name	chris pierce	Phone#	
Address	11573 86th ave n	One Call Ticket#	
City & Zip	maple grove,55369		
Location/Directions	mills creek development		
Description of Work or Special Instructions	plow in 130ft fiber drop, with 20ft driveway bore		

Held Order	N	Permit:	Notes	Bore:	Y	CBR#	4804588300
Tech Name and Tech #	pat nathe		Employee Contact#	6127159213			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot#	33	SEB3-22	BSW-3 & plow plcmt	
		SEB3-22T	BSW-3 & hand dig plcmt	
Ped#	9999	SEPCUTOVER	CUTOVER BSW	
Parish/County	Hennepin	BM83	BSW guard at house	1
		XXSEB-GL	Remove temp drop	
Township:		BM61(1.25)SEB	BSW Bore footage	20
Section		SEBO PER FT LBR	Fiber & plow plcmt	
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt	130
		SEB6-22	BSW-6 & plow plcmt	
		BM2(5/8)(8)	Ground Rod	
		Trip Charge	Trip Charge	1
		BM61(3)D-Rock CBL	Rock Boring	
		Permit	Permit	
Nearest cross st.	forestview		Plat Page	Map#



Originated By:	pat nathe	Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	