

Revised 2-10-2020	State	MN	Contractor	MN Outstate	CMS#	20028461
----------------------	-------	----	------------	-------------	------	----------

CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	1569777342	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	JIM REDING	Phone#	7634163844		
Address	17176 66TH PL N		One Call Ticket#		
City & Zip	MAPLE GROVE MN 55311				
Location/Directions	66TH AND LAWNSDALE				
Description of Work or Special Instructions					

Held Order	N	Permit:	Y	Bore:	Y	CBR#	6126867592
Tech Name and Tech #	DEX KOEPP AB71973			Employee Contact#	6513025304		

Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	70	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	80	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.			Plat Page	Map#



Originated By:	AB71973	Date:	2/21/20	Completed By:	_____	Date:	_____
Authorized By: (SRO)	_____	Date:	_____	Inspected By:	_____	Date:	_____
Authorized By: (MRO)	_____	Date:	_____		_____		_____

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	