



Local
CMS#

CMS#

16243208 PERMIT


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name Ashley Osterberg Phone# _____
 Address 12091 99th Ave N One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions Plow 145 ft from Ped to NED.

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes X No ___ CBR# _____
 Employee Name Kris Townsend Employee Contact# 612-4303133

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County <u>Hennipen</u>					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # 5449034
SKETCH Tax Code _____



Originated By: Evans Date: 7/1/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____