

Revised 2-10-2020	State MN	Contractor MN Outstate	CMS# 20052721
CenturyLink BSW Order/Maintenance Work Authorization			
Company	Exchange Name MPGVMNXA	Service Order# 1573416157	
Work Activity	Capital N	Maintenance Y	
Customer Name		Phone# 7634161833	
Address 6939 XANTHUS LN N		One Call Ticket#	
City & Zip	MAPLE GROVE 55311		
Location/Directions			
Description of Work or Special Instructions			
Held Order	N	Permit: Y	Bore: Y
Tech Name and Tech # DEX KOEPP AB71973		Employee Contact# 6513025304	CBR# 7638430071
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity
	Description	Notes	
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt	
	SEB3-22T	BSW-3 & hand dig plcmt	
Ped#	SEPCUTOVER	CUTOVER BSW	1
Parish/County	BM83	BSW guard at house	
	XXSEB-GL	Remove temp drop	250
Township:	BM61(1.25)SEB	BSW Bore footage	50
Section	SEBO PER FT LBR	Fiber & plow plcmt	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	40
	SEB6-22	BSW-6 & plow plcmt	
	BM2(5/8)(8)	Ground Rod	
	Trip Charge	Trip Charge	1
	Permit	Permit	1
Nearest cross st.		Plat Page	Map#
Originated By:	AB71973	Date:	4/3/20
Completed By:		Date:	
Authorized By: (SRO)		Date:	
Inspected By:		Date:	
Authorized By: (MRO)		Date:	
Email sketch to:			
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	