


Revised 2-10-2020 State **MN** Contractor **MN Outstate** CMS# **20032240**

CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	MPGVMNXA	Service Order#	1570396472
Work Activity	Fiber-Buried		Capital	Y
Customer Name	JENNIFER YICK		Maintenance	N
Address	18987 72ND PL N		Phone#	7634162789
City & Zip	CORCORAN			
Location/Directions	RUSH CREEK COMMONS			
Description of Work or Special Instructions				

Held Order	N	Permit:	N	Bore:	Y	CBR#	6123253664
Tech Name and Tech #	DEX KOEPP AB71973			Employee Contact#	6513025304		

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	50	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	20	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit		Any placement within the ROW requires a permit
Nearest cross st.			Plat Page	Map#



Originated By:	AB71973	Date:	2/28/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	