

| | | | | |
|----------------------|-------------|------------------------|------|------------------------|
| Revised 2-10-2020 | State MN | Contractor MN Metro | CMS# | 20057682 - HELD |
|----------------------|-------------|------------------------|------|------------------------|

CenturyLink BSW Order/Maintenance Work Authorization

| | | | |
|---|---------------------------|----------------|------------|
| Company | Exchange Name MPGVMNXA | Service Order# | 1573827827 |
| Work Activity | Fiber-Buried | Capital | Y |
| Customer Name | CENTURYLINK SIMPLEPAY | Maintenance | N |
| Address | 10792 SUNDANCE BLVD | Phone# | 7634160292 |
| City & Zip | DAYTON 55369 | | |
| Location/Directions | | | |
| Description of Work or Special Instructions | | | |

| | | | | | | | |
|----------------------|-------------------|---------|-------------------|------------|---|------|------------|
| Held Order | Y | Permit: | Y | Bore: | Y | CBR# | 7158282526 |
| Tech Name and Tech # | DEX KOEPP AB71973 | | Employee Contact# | 6513025304 | | | |

| Sketch (Include Cntr Line & Pedestal) | Material/Labor Units | | Footage/Quantity | Comments |
|--|----------------------|------------------------|------------------|--|
| | Description | Notes | | |
| Cntr Line foot | SEB3-22 | BSW-3 & plow plcmt | | |
| | SEB3-22T | BSW-3 & hand dig plcmt | | |
| Ped# | SEPCUTOVER | CUTOVER BSW | | |
| Parish/County | BM83 | BSW guard at house | 1 | |
| | XXSEB-GL | Remove temp drop | 400 | Footage when temp can't be re-used |
| Township: | BM61(1.25)SEB | BSW Bore footage | 72 | |
| Section | SEBO PER FT LBR | Fiber & plow plcmt | | |
| Range | SEBO PER FT LBR T | Fiber & hand dig plcmt | 140 | |
| | SEB6-22 | BSW-6 & plow plcmt | | |
| | BM2(5/8)(8) | Ground Rod | | |
| | Trip Charge | Trip Charge | 1 | |
| | Permit | Permit | 1 | Any placement within the ROW requires a permit |
| Nearest cross st. | | | Plat Page | Map# |



| | | | | | | | |
|----------------------|---------|-------|--------|---------------|--|-------|--|
| Originated By: | AB71973 | Date: | 4/9/20 | Completed By: | | Date: | |
| Authorized By: (SRO) | | Date: | | Inspected By: | | Date: | |
| Authorized By: (MRO) | | Date: | | | | | |

Email sketch to:

| | | | |
|---|--|---|--|
| 1. Distance of the bury in Right-of-Way | | 3. Distance to the nearest intersection | |
| 2. Distance from the terminal to the centerline | | 4. Nearest State Hwy mile marker | |