

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	20088037 - HELD	
CenturyLink BSW Order/Maintenance Work Authorization							
Company	Exchange Name	MPGVMNXA			Service Order#	1576524652	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N		
Customer Name	CENTURYLINK SIMPLEPAY			Phone#	7634162269		
Address	7399 INLAND LN N			One Call Ticket#			
City & Zip	MAPLE GROVE 55311						
Location/Directions							
Description of Work or Special Instructions							
Held Order	Y	Permit:	Y	Bore:	Y	CBR#	612-616-6500
Tech Name and Tech #	DEX KOEPP AB71973			Employee Contact#	6513025304		
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units			Footage/Quantity	Comments		
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	SEPCUTOVER	CUTOVER BSW					
Parish/County	BM83	BSW guard at house		1			
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used		
Township:	BM61(1.25)SEB	BSW Bore footage		70			
Section	SEBO PER FT LBR	Fiber & plow plcmt					
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		50			
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	Trip Charge	Trip Charge		1			
	Permit	Permit		1	Any placement within the ROW requires a permit		
Nearest cross st.				Plat Page		Map#	
Originated By:	AB71973	Date:	5/21/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					
Email sketch to:							
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					