

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	20129409 - HELD
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name	OSSEMNXO			Service Order#	1580140202
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N	
Customer Name	TEJA SWINI MADA			Phone#	7633151047	
Address	8175 EVERGREEN LN N			One Call Ticket#		
City & Zip	MAPLE GROVE 55369					
Location/Directions						
Description of Work or Special Instructions	HARD END IN PED. PRIVATE ROW					
Held Order	Y	Permit:	N	Bore:	Y	CBR# 4082504064
Tech Name and Tech #	DEX KOEPP AB71973			Employee Contact#	6513025304	
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments	
	Description	Notes				
Cntr Line foot#	SEB3-22	BSW-3 & plow plcmt				
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	SEPCUTOVER	CUTOVER BSW				
Parish/County	BM83	BSW guard at house		1		
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage		50		
Section	SEBO PER FT LBR	Fiber & plow plcmt				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		100		
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	Trip Charge	Trip Charge		1		
	Permit	Permit			Any placement within the ROW requires a permit	
Nearest cross st.		Plat Page		Map#		
Originated By:	AB71973	Date:	7/24/20	Completed By:		Date:
Authorized By: (SRO)		Date:		Inspected By:		Date:
Authorized By: (MRO)		Date:				
Email sketch to:						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection				
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker				