


		Local Exch#			CMS#	16193051 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization							
Company	T600	Exchange				Service Order#	
Work Activity				Capital	Y	Maintenance	Y
Customer Name					Phone#	7634201324	
Address	7201 Deerwood Ln N				One Call Ticket#		
City & Zip	Maple Grove						
Location/Directions							
Description of Work or Special Instructions	Need to bury 125 of 3 pair Bore 32' under driveway NID on north side of house						
Held Order ?		Permit:		No	Bore:	y	NO
Employee Name	Tom Ferrarini				Employee Contact#	6129169351	
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units			Est	Actual	Placed by	
	Description	Notes		Qty.	Qty	(Foreman/Crew Name)	
Cntr Line foot	SEB3-22	Place 3 pair BSW		125'			
	SEPCUTOVER	CUTOVER BSW		y			
Parish/County	Washing	BM83	BSW guard at house		y		
		XXSEB-GL	Remove temp drop		y		
Township:		BM61(1.5)D	BSW Bore required		32'		
Section		SEB3-22T	Hand Dig				
Range		SEBOP2	Fiber Drop				
Nearest cross st.	71St PI N				Plat Page		Map#
Damaged facility #							
SKETCH							



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	
Inspection Notes: MetroBSW@centurylink.com			
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline:		4. Nearest State Hwy mile marker	