

Revised 2-10-2020	State MN	Contractor MN Metro	CMS# 20131826 - HELD
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>			
Company	Exchange Name MPGVMNXA	Service Order# 1580364162	
Work Activity	Fiber-Buried	Capital Y	Maintenance N
Customer Name	CENTURYLINK SIMPLEPAY	Phone# 7634165457	
Address	12698 82ND PL N	One Call Ticket#	
City & Zip	MAPLE GROVE 55369		
Location/Directions			
Description of Work or Special Instructions	HARD END IN PED		
Held Order	Y	Permit: Y	Bore: Y
Tech Name and Tech #	DEX KOEPP AB71973	Employee Contact#	6513025304
CBR#	6128198823		
Sketch	Material/Labor Units		Footage/Quantity
(Include Cntr Line & Pedestal)	Description	Notes	Comments
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt	
	SEB3-22T	BSW-3 & hand dig plcmt	
Ped#	SEPCUTOVER	CUTOVER BSW	
Parish/County	BM83	BSW guard at house	1
	XXSEB-GL	Remove temp drop	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	130
Section	SEBO PER FT LBR	Fiber & plow plcmt	200
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	
	SEB6-22	BSW-6 & plow plcmt	
	BM2(5/8)(8)	Ground Rod	
	Trip Charge	Trip Charge	1
	Permit	Permit	1
Nearest cross st.		Plat Page	Map#
Originated By:	AB71973	Date:	7/30/20
Completed By:		Date:	
Authorized By: (SRO)		Inspected By:	
Authorized By: (MRO)		Date:	
Email sketch to:			
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	