

CenturyLink BSW Order/Maintenance Work Authorization

Company	Exchange Name	Service Order#
Work Activity	Fiber-Buried	Capital <input type="checkbox"/> N Maintenance <input type="checkbox"/> Y
Customer Name	JOHN & PAT RASMUSSEN	Phone# (763) 425-7719
Address	10453 108TH AVE N	One Call Ticket#
City & Zip	MAPLE GROVE, MN	
Location/Directions	GPS	
Description of Work or Special Instructions	see sketch for details, optitap at nid and SC at dog house	

Held Order	<input type="checkbox"/> N Permit: <input type="checkbox"/> Y Bore: <input type="checkbox"/> Y	CBR# 763-438-3453
Tech Name and Tech #	aa10109	Employee Contact# 7632288645

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped# dog house	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop	500	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	50	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt	130	
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	GPS		Plat Page	Map#



Originated By: AA10109 Date: 8/19/20 Completed By: _____ Date: _____
 Authorized By: (SRO) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (MRO) _____ Date: _____

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker