

Revised 2-10-2020	State MN	Contractor MN Metro	CMS#	20151176 - HELD
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance
Customer Name	chris lacono		Phone#	(763) 416-4165
Address	7733 fountains ln		One Call Ticket#	
City & Zip	maple grove			
Location/Directions	III			
Description of Work or Special Instructions	plow in fiber drop 120ft with 55ft of boring			
Held Order	Y	N	Permit: Y N	Bore: Y N
Tech Name and Tech #	p.nathe		Employee Contact#	6127159213
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	55	
Section	SEBO PER FT LBR	Fiber & plow plcmt	120	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.	everest ln		Plat Page	Map#

Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (SRO) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (MRO) _____	Date: _____		

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker