

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	20080741
----------------------	-------	----	------------	----------	------	----------

**CenturyLink BSW Order/Maintenance Work Authorization**

Company	Exchange Name	PLMOMNFE	Service Order#	vn255022	
Work Activity	Buried Cable-Metallic	Capital	N	Maintenance	Y
Customer Name	alex cross		Phone#	(763) 559-2445	
Address	14681 bass lake rd		One Call Ticket#		
City & Zip	maple grove				
Location/Directions					
Description of Work or Special Instructions					

Held Order	N	Permit:	Y	Bore:	N	CBR#	9524548918
Tech Name and Tech #	rico 838		Employee Contact#	6128163956			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt	320	
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped# 6644j	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop	200	Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage		
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit

Nearest cross st.		Plat Page		Map#	
-------------------	--	-----------	--	------	--



Originated By:		Date:	5/11/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	