

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	20160413 - HELD
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name			Service Order#		
Work Activity	Drop-Buried Copper			Capital	N	Maintenance Y
Customer Name	PAUL IPSEN			Phone#	(763) 493-5769	
Address	9884 HEMLOCK WAY N			One Call Ticket#		
City & Zip	MAPLE GROVE, MN					
Location/Directions	GPS					
Description of Work or Special Instructions	emergency placement					

Held Order	N	Permit:	Y	Bore:	Y	CBR#	7634935769
Tech Name and Tech #	aa10109			Employee Contact#	7632288645		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments		
	Description		Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	544 9031	SEPCUTOVER	CUTOVER BSW	1			
Parish/County		BM83	BSW guard at house	1			
		XXSEB-GL	Remove temp drop		Footage when temp can't be re-used		
Township:		BM61(1.25)SEB	BSW Bore footage	130			
Section		SEBO PER FT LBR	Fiber & plow plcmt	175			
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt				
		SEB6-22	BSW-6 & plow plcmt				
		BM2(5/8)(8)	Ground Rod				
		Trip Charge	Trip Charge	1			
		Permit	Permit	1	Any placement within the ROW requires a permit		
Nearest cross st.	99th pl n			Plat Page		Map#	



Originated By:	aa10109	Date:	9/10/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	