


CenturyLink BSW Order/Maintenance Work Authorization

Company		Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Drop-Buried Copper	Capital	N	Maintenance	Y
Customer Name	Tiffany Giese	Phone#	(763) 494-0159		
Address	13980 90th pl		One Call Ticket#		
City & Zip	maple grove				
Location/Directions	mpgv				
Description of Work or Special Instructions	plow in new drop. 115ft with 35 road bore				

Held Order	Y	N	Permit:	Y	N	Bore:	Y	N	CBR#	6129403073
Tech Name and Tech #	p.nathe					Employee Contact#	6127159213			
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units					Footage/Quantity	Comments			
		Description	Notes							
Cntr Line foot#	SEB3-22			BSW-3 & plow plcmt		115				
	SEB3-22T			BSW-3 & hand dig plcmt						
Ped#	837-9005	SEPCUTOVER		CUTOVER BSW						
Parish/County	BM83		BSW guard at house							
	XXSEB-GL		Remove temp drop			Footage when temp can't be re-used				
Township:	BM61(1.25)SEB		BSW Bore footage		35					
Section	SEBO PER FT LBR		Fiber & plow plcmt							
Range	SEBO PER FT LBR T		Fiber & hand dig plcmt							
	SEB6-22		BSW-6 & plow plcmt							
	BM2(5/8)(8)		Ground Rod							
	Trip Charge		Trip Charge		1					
	Permit		Permit		1	Any placement within the ROW requires a permit				
Nearest cross st.	rice lake rd					Plat Page			Map#	



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (SRO) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (MRO) _____	Date: _____		

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker