

Revised 2-10-2020	State MN	Contractor MN Metro	CMS#	20154257
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name STMCMNXS	Service Order#		
Work Activity	Drop-Buried Copper	Capital	N	Maintenance Y
Customer Name	JAMES JOHNSON	Phone#	JAMES JOHNSON	
Address	9875 HEMLOCK WAY N	One Call Ticket#		
City & Zip	Maple Grove, MN			
Location/Directions				
Description of Work or Special Instructions	Bore 70 ft of 3 pair copper from ped to white flag. Splice will need to be completed once bore is			
Held Order	N	Permit:	Y	Bore: Y
Tech Name and Tech #	Kris Townsend	Employee Contact#	612-715-9069	
Sketch	Material/Labor Units		Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	70	
Section	SEBO PER FT LBR	Fiber & plow plcmt		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	Trip Charge	Trip Charge	1	
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.		Plat Page		Map#

NID is behind deck but should be able to get to it if needed. Push 3 pr to back side. Customer will move wood.

Originated By:	Townsend	Date:	9/1/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker