

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	20188859
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name			Service Order#		
Work Activity	Fiber-Buried			Capital	N	Maintenance Y
Customer Name	MICHAEL SULLIVAN			Phone#		(763) 420-2110
Address	10475 VALLEY FORGE LN N			One Call Ticket#		
City & Zip	MAPLE GROVE, MN					
Location/Directions	gps					
Description of Work or Special Instructions				see sketch for details		

Held Order		N	Permit:	Y	Bore:	Y	CBR#	763-746-6066
Tech Name and Tech #	aa10109			Employee Contact#		7632288645		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments			
	Description		Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt						
	SEB3-22T	BSW-3 & hand dig plcmt						
Ped#	97954	SEPCUTOVER	CUTOVER BSW	1				
Parish/County		BM83	BSW guard at house					
		XXSEB-GL	Remove temp drop		Footage when temp can't be re-used			
Township:		BM61(1.25)SEB	BSW Bore footage	86				
Section		SEBO PER FT LBR	Fiber & plow plcmt	186				
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt					
		SEB6-22	BSW-6 & plow plcmt					
		BM2(5/8)(8)	Ground Rod					
		Trip Charge	Trip Charge	1				
		Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.	gps			Plat Page	Map#			



Originated By:	aa10109	Date:	10/15/20	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	