

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	20193328 - HELD
CenturyLink BSW Order/Maintenance Work Authorization						
Company	Exchange Name	MPGVMNXA			Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance		
Customer Name	Brian French			Phone#	(763) 657-1881	
Address	12569 85th PI N			One Call Ticket#		
City & Zip	Maple Grove Mn					
Location/Directions						
Description of Work or Special Instructions	Plow 90 ft of fiber from ped to nid. 50 ft right of way bore required					
Held Order	Y	Permit:	Y	Bore:	Y	CBR# 7635683780
Tech Name and Tech #	Don Evans			Employee Contact#	6124303133	
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units			Footage/Quantity	Comments	
	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt				
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	SEPCUTOVER	CUTOVER BSW				
Parish/County	BM83	BSW guard at house		1		
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage		90		
Section	SEBO PER FT LBR	Fiber & plow plcmt		50		
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt				
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	Trip Charge	Trip Charge		1		
	Permit	Permit		1	Any placement within the ROW requires a permit	
Nearest cross st.				Plat Page		Map#
Originated By:	Don Evans	Date:	10/21/20	Completed By:		Date:
Authorized By: (SRO)		Date:		Inspected By:		Date:
Authorized By: (MRO)		Date:				
Email sketch to:						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection				
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker				