



Local
CMS#

16086783 HELD ORDER PERMIT


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital Maintenance _____
 Customer Name Kristine Dupree Phone# 763-315-5374
 Address 9608 105 Av. N., Maple Grove One Call Ticket# _____
 Location/Directions _____
 Description of Work or Special Instructions _____

DOR/TOG Yes ___ No Permit: Yes No ___ Bore: Yes ___ No CBR# G12-710-7592
 Employee Name Brandon Smith Employee Contact# 612-296-7599

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County _____					
Hennipen _____					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH _____



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____		
Inspection notes: _____			