Perm: + Zaha Design

Hot!!: JT 21762

Issued 7-Ray 11/22/16

Comcast

Plant Maintenance Rec	uest		Job number	NW452
Node DA161	City	Maple Grove	Date	1/22/2016
Address 17451 83rd Ave Cross Street				
Maint tech Name:	Joe Krick	Tech #	1523 Phone:	(612) 875-6448
Span type Span (tem	nped) 🗸 Span (no temp	o) Digup	Other Spring	
Priority 1 📝 a.) Cu	stomer Impacting Issue b.) \	Vulnerabe temp c.) TIE r	elated ticket	7
2 a.) Aerial temp cables b.) Any temp - no liability issues				
3 a.) Identified cables - no customer impact b.) Leaks - no customer impact				
Work is an Emergency (outage issue) Emergency Normal				
Work is a:				
Util	ity Violation Storm Da	mage Leakage	Other	
MDU? (Attachments, lockboxes, cable on the roof)				
Type of Cable Size: 625 Aerial UG Bare UG Duct Self Support				
Footage: Aeria	1	Underground	70'	
Bore Required	es 🗌 No 💮 If yes, i	what type and how man		1 Driveway
Cause for referral: RTM Leakage Rapid Resolve (Flux) Damage/Outage NH/MH				
(check one) Priority plant fault LPI Service Call Alert PI Ticket Other				
Evalain Damaga				
Explain Damage:				
Cable is damaged under the driveway. There is no leak, likely a splice has water in it. Replace from the 23v tap, back 70'. Dig up and splice. Cable is located and marked where to run the new cable to and dig.				
back 70. Dig up and splice. Cable is located and marked where to run the new cable to and dig.				
Maintenance Department Use Only				
Date Received		Capitol	Yes No	Maint complete
Total Tech Hours		Techs		,
A Highlighted plant map must be attached				
To help expedite this maintenance request, information on this form needs to be filled out completely and				
signed by a technician and a supervisor requesting the repair.				
Tech Signature	Joe Krick	Te	ech #1523	3 Date 1/22/2016
Supervisor Signature			71-	
		ruction Departme	ent Use Only	_
Date received	Project			Construction Completed
Coordinator Signature		Supervisor Sig	nature	

