

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	21004319
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>						
Company	Exchange Name	OSSEMNXO			Service Order#	T100041015.0001
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N	
Customer Name	BRETT GODA			Phone#	(763) 425-0315	
Address	10395 QUAKER LN N			One Call Ticket#		
City & Zip	MAPLE GROVE, MN 55369-2964					
Location/Directions	gps					
Description of Work or Special Instructions	see sketch for details					

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	952-221-8980
Tech Name and Tech #	AA10109			Employee Contact#	7632288645		
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments			
	Description	Notes					
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt					
	SEB3-22T	BSW-3 & hand dig plcmt					
Ped#	mst	SEPCUTOVER	1				
Parish/County	BM83	BSW guard at house	1				
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage	78				
Section	SEBO PER FT LBR	Fiber & plow plcmt	137				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt					
	SEB6-22	BSW-6 & plow plcmt					
	BM2(5/8)(8)	Ground Rod					
	Trip Charge	Trip Charge	1				
	Permit	Permit	1	Any placement within the ROW requires a permit			
Nearest cross st.	see sketch for details		Plat Page	Map#			



Originated By:	AA10109	Date:	1/11/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	