


CenturyLink BSW Order/Maintenance Work Authorization

Company		Exchange Name	MPGVMNXA	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	
Customer Name	David Jones	Phone#	(763) 425-0414	One Call Ticket#	
Address	8155 Central Parkway N				
City & Zip	Maple Grove Mn				
Location/Directions					
Description of Work or Special Instructions	Plow 70 ft of fiber from ped to nir. 650 ft right of way bore required				

Held Order		N	Permit:	Y	Bore:	Y	CBR#	8109316449
Tech Name and Tech #	Don Evans			Employee Contact#	6124303133			
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units			Footage/Quantity	Comments			
	Description	Notes						
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt						
	SEB3-22T	BSW-3 & hand dig plcmt						
Ped#	SEPCUTOVER	CUTOVER BSW		1				
Parish/County	BM83	BSW guard at house		1				
	XXSEB-GL	Remove temp drop		150	Footage when temp can't be re-used			
Township:	BM61(1.25)SEB	BSW Bore footage		65				
Section	SEBO PER FT LBR	Fiber & plow plcmt		10				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt						
	SEB6-22	BSW-6 & plow plcmt						
	BM2(5/8)(8)	Ground Rod						
	Trip Charge	Trip Charge		1				
	Permit	Permit		1	Any placement within the ROW requires a permit			
Nearest cross st.				Plat Page		Map#		



Originated By:	Don Evans	Date:	3/8/21	Completed By:	_____	Date:	_____
Authorized By: (SRO)	_____	Date:	_____	Inspected By:	_____	Date:	_____
Authorized By: (MRO)	_____	Date:	_____		_____		_____

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker