

Revised 2-10-2020	State	MN	Contractor	MN Metro	CMS#	21061665
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>						
Company	Exchange Name	HBNGMNHI			Service Order#	14081195
Work Activity				Capital	Maintenance	
Customer Name	Travis Gasparick			Phone#	(763) 425-2490	
Address	11272 100th PI N			One Call Ticket#		
City & Zip	Maple Grove 55369					
Location/Directions						
Description of Work or Special Instructions						
Held Order	Y	N	Permit:	Y	N	Bore:
						CBR# 7634252490
Tech Name and Tech #	Mariano Musngi Tech181			Employee Contact#	3108637755	
Sketch (Include Cntr Line & Pedestal)	Material/Labor Units			Footage/Quantity	Comments	
	Description	Notes				
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		1		
	SEB3-22T	BSW-3 & hand dig plcmt				
Ped#	SEPCUTOVER	CUTOVER BSW				
Parish/County	BM83	BSW guard at house				
	XXSEB-GL	Remove temp drop			Footage when temp can't be re-used	
Township:	BM61(1.25)SEB	BSW Bore footage		60		
Section	SEBO PER FT LBR	Fiber & plow plcmt				
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt				
	SEB6-22	BSW-6 & plow plcmt				
	BM2(5/8)(8)	Ground Rod				
	Trip Charge	Trip Charge				
	Permit	Permit			Any placement within the ROW requires a permit	
Nearest cross st.	Balsam			Plat Page	Map#	

  
  

Originated By:		Date:		Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	