

Revised 03-10-2021	State MN	Contractor MN Metro	CMS#	21075587 - HELD
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name MPGVMNXA	Service Order#		
Work Activity Fiber-Buried	Capital	Y	Maintenance	
Customer Name Pratik Patel	Address 8092 Central parkway N	Phone#	(763) 416-3608	
City & Zip	Maple Grove MN			
Location/Directions	Description of Work or Special Instructions Plow 100 f tof fiber from ped to nid. 60 ft right of way bore required.			
Held Order	Y	Permit:	Y	Bore:
Tech Name and Tech # Don Evans	Employee Contact#	6124303133		
Sketch	Material/Labor Units		Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt		
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	SEPCUTOVER	CUTOVER BSW		
Parish/County	BM83	BSW guard at house	1	
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	BM61(1.25)SEB	BSW Bore footage	60	
Section	SEBO PER FT LBR	Fiber & plow plcmt	100	
Range	SEBO PER FT LBR T	Fiber & hand dig plcmt		
	SEB6-22	BSW-6 & plow plcmt		
	BM2(5/8)(8)	Ground Rod		
	SEBO-COIL	Fiber Coil	1	Coil excess on Fiber drop add 1 unit
	Permit	Permit	1	Any placement within the ROW requires a permit
Nearest cross st.		Plat Page		Map#

Central Park way N

Originated By:	Don Evans	Date:	5/10/21	Completed By:		Date:	
Authorized By: (SRO)		Date:		Inspected By:		Date:	
Authorized By: (MRO)		Date:					

Email sketch to:

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	